2022 Sept 22 -- NQR Turbo pump ILE2A1:TP1 V-551 failed.

Loud bearing noises. Dimo happened to be there and confirmed problem. Shut down ~Aug 24 2022.

Replacement exchange part provided by Edi Dalla Valle, Vacuum group.

Replaced by DV, RA. Work Permit: **I2022-09-22-2** Old : Serial IT13166209 model RP9698923 mfgdate: 2018 07



New: Serial IT22291024 model EX9698923 mfgdate: 2022 Jul 22

